## **CES Activities to Complete: 3/5/15**

1. Wastewater Treatment Tank Area

Sludge Removal: LIME Acid Removal: R02, PT6 Liquid Removal: R01 Piping: Remove Materials

Secondary Containment: Final Cleanup

2. Aboveground Storage Tank Area

Liquid/Sludge Removal: ST1 Acid Removal: PT1, PT2 Liquid Removal: PT3 Piping: Remove Materials

Secondary Containment: Remove contaminated Sand and Final Cleanup

3. Frac Tank Waste Disposal

FT1004/FT1002 (Lonestar Ecology)

FT30335

FT215012/FT33527 (Sludge Removal)

Contact Dana Transport and Have Them Pick up FT's

- 4. Bulk Poly Tanks, Totes, Vats, Drums, Misc Containers, Carbon, Supersacks
- 5. Remove Material (Liquids/Solids) form Large VAT South of ASTs
- 6. Place large pipe with valve out the South Pond Area for Storm Water Drainage;
- 7. Main Warehouse

Chop Saw Piping in Trench and Remove Trench Solids Clean Contaminated Solids from Warehouse Floor

8. Truck Wash Bay, Shed, Former Shed:

Truck Wash Bay: Remove Liquids/Solids and from Sump and Trenches and Final Clean Shed: Remove Liquids/Solids from Sump and Drains and Final Clean Former Shed: Remove Liquids/Solids from Sumps and Trenches and Final Clean

- 9. Clean Empty Poly Tanks, Totes, Drums, Vats, etc.
- 10. Dispose of Containerized Wastes (vac boxes, fracs, rolloffs)